

4/16 ~~10~~ am Field notes

Completed "901" East 2142

got ~~config~~ ^{config} files "CCFL-2142-20220402.xml"

got lens position wide! Zoom 0 MF 188

" Zoom 2 Zoom 1000 MF 250

updated firmware it took less than a minute

at 1044 am, I stopped the video at 30 minutes

The green circle of death is still there. Flight
limited session to 20%

did not need to do 13 for video, did for zoom

got config files "CCFL 2142 20220406(1).xml"

discovered East - not saving files at 1123

Completed "1027" West 2141 58% full

got old config files "CCFL-2141-20220406.xml"

got lens position wide! Zoom 0 MF 204

Zoom 1 Zoom 1000 MF 156 no picture

updated firmware took less than 2 minutes

within 2 minutes on video

The unit: dropped

got config files "CCFL-2141-20220406(1).xml"

checked camera settings

wide Zoom 0 MF 204

Zoom Zoom 1000 MF 156

logged off at 1157 am