

5/29/22 afternoon

redo East Cam
from wave up & etc

3:01 pm connected to East from Road below
on M1 Mac

Set power ON full time

3:06²⁰ begin DL conty. file

06²⁵ done " " "

sat w/fti connection to not automatic

3:00¹⁰ start update

12⁰⁰ 50% - wheel

12⁵⁰ begin spinning wheel

13⁴⁰ no w/fti visible

(I did not watch it do 3 appear, it
likely happened earlier

15³⁵ East w/fti availability just showed up

16³⁰ still spinning wheel

17⁰⁰ connect to East w/fti
went right to The Dashboard

18⁰⁰ confirm V 2,7,7,d

19³⁰ begin DL Log - files

23⁵⁵ End " " " CFC. 219 - 4, download "

25⁰⁰ set to deep sleep

3:35⁰⁰ w/fti dis connects